


DRAWING A-04 – Guy Wire Requirements



NOTES:

1. Licensee shall be responsible for procuring and installing all anchors and guy wires to support the additional stress placed on Licensor's poles by Licensee's attachments.
2. Anchors and guy wires must be set on each Pole where there is a turn or angle and on all dead-end Poles.
3. Licensee may not place guy wires on the anchors of Licensor or other Attaching Entity without prior written consent of all Attaching Entities and anchor owners.
4. No Attachment may be installed on a Pole until all required guys and anchors are installed, nor may any Attachment be modified or relocated in such a way as will materially increase the stress or loading on Poles until all required guys and anchors are installed.
5. Licensee's down guys shall not be bonded to ground or neutral wires of Pole and shall not provide a current path to ground from the Pole ground or power system neutral.
6. No communications power supply shall be mounted on Poles.
7. Licensee's attachments on Poles including metal attachment clamps and bolts, metal crossarm supports, bolts and other equipment must be attached so as to maintain the minimum separations specified in the NESC and in the Licensor's drawings and specifications.